


SERRATED BRONZE WEDGE

MODEL LVSW



DESCRIPTION

Serrated bronze wedges are provided for electrical thawing, two per joint, for 3-inch through 12-inch pipe, and four, for larger diameter pipe. Each wedge is driven into the opening between the plain end and the bell until snug. When four wedges are used on pipes larger than 12 inches, they are inserted side by side, in pairs.



A (In.)	B (In.)	WEIGHT (Lbs.)	MATERIAL
.53	1.0	.42	C89836 Copper Bismuth Alloy Lead-free

WARNING: Electrical thawing of buried pipes should never be attempted by inexperienced people. The large currents necessary to thaw a frozen pipe can cause serious damage to electrical systems that are grounded to the buried pipes, and there is a serious risk, of personal injury or electrocution if proper precautions are not taken.

PROJECT	APPROVAL STAMP
PROJECT:	<input type="checkbox"/> APPROVED
ADDRESS:	<input type="checkbox"/> APPROVED AS NOTED
ENGINEER:	<input type="checkbox"/> NOT APPROVED
SUBMITTAL DATA:	REMARKS:
NOTES 1:	
NOTES 2:	